

**Flood Control Project Maintenance
Levee Inspections**

Fall 2012 Levee Maintenance Deficiency Summary Report

Overall LMA & Unit Ratings, including DWR Erosion Survey

San Joaquin River Basin

RD2058	Overall LMA	Total LMA						
Reclamation District No. 2058	Rating	Miles						
Pescadero	A	6.71						
Rated Item	Maintenance Deficiency				Enforcement		Design & System Obsolescence	
	M Miles	U Miles	M + 4U Miles	Threshold %	M Miles	U Miles	M Miles	U Miles
<i>Earthen Levee</i>								
Vegetation	0.06		0.06	0.89%				
Encroachments	0.01		0.01	0.15%		0.02		
Animal Control	0.01		0.01	0.15%				
<i>Supplemental</i>								
DWR Erosion Survey	0.05		0.05	0.75%				
<i>LMA Totals:</i>	0.13	0.00	0.13	1.94%	0.00	0.02	0.00	0.00

**Flood Control Project Maintenance
Levee Inspections**
LMA District Cover Sheet
Fall 2012 Levee Inspection Results

Reclamation District No. 2058 Pescadero

	Spring (March - May)	Summer ** (June - August)	Fall (September - November)	Winter ** (December - February)
* Overall LMA Rating (Fall Only)			A	

** Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

*
SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

**Flood Control Project Maintenance
Levee Inspections**

Unit Cover Sheet

Fall 2012 Levee Inspection Results

Reclamation District No. 2058 Pescadero

Waterway			Bank	Unit Miles
Unit No. 01 Paradise Cut			Left	6.71
	Spring (March - May)	Summer (June - August)	(September - November) Fall	Winter (December - February)
Unit Maintenance Rating (Fall Only)			A	
Date of Inspection	03/28/2012 - 03/28/2012		11/06/2012 - 11/06/2012	
DWR Inspector	Jim Eto		Maksim Khashchuk	
Accompanied By	Greg Pombo		Greg Pombo	

Summer & Winter Inspections

The Local Maintaining Agency (LMA) is responsible for summer and winter inspections. The LMA is required to submit a report regarding summer and winter inspections to the California Department of Water Resources (DWR).

DWR must be informed on the:

- a) completion of the inspection
- b) any changes other than the results of normal maintenance
- c) corrections to deficiencies noted in this report

If additional items are noted, further documentation of those items must also be submitted.

The LMA should submit this information to DWR using the LMA web application tool available at:

<http://cdec.water.ca.gov/lma.html>

If the LMA is unable to submit information on this webpage, please contact DWR for assistance.

The LMA should submit the information and any associated documentation by September 30 for summer inspections and March 31 for winter inspections.

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 2058 Pescadero

Waterway				Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut				Left	6.71	11/06/2012 11/06/2012	Maksim Khashchuk

LMR No.	Levee Mile		Category	Item	* Location	** Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	Photo
1			Earthen Levee	Operations & Maintenance Manuals	WS	A Ma		°	°	75
DWR ID: DWR_RD2058_01_s_2012_75										
2			Earthen Levee	Emergency Supplies & Equipment	WS	A Ma		°	°	76
DWR ID: DWR_RD2058_01_s_2012_76										
3			Earthen Levee	Flood Preparedness & Training	WS	A Ma	Inspector Comments: Written action plan was presented to me along with supporting documentation (phone list, contacts, etc.).	°	°	77
DWR ID: DWR_RD2058_01_s_2012_77										
4	0.42	0.42	Earthen Levee	Vegetation	WS	M Ma	V2 : Remove the wild growth other than native grasses from the levee slopes. Inspector Comments: Thick vegetation at this point, needs to be removed.	37.803813 ° -121.415578 °	37.803813 ° -121.415578 °	8 Y
DWR ID: DWR_RD2058_01_s_2012_8										
5	0.73	0.73	Earthen Levee	Encroachments	LS A/W	PI : Pipe Ma		37.801952 ° -121.411002 °	37.801952 ° -121.411002 °	3 Y
DWR ID: DWR_RD2058_01_f_2012_3										
6	0.96	0.96	Earthen Levee	Encroachments	LS	M Ma	PR : Prunings	37.801428 ° -121.406495 °	37.801428 ° -121.406495 °	4 Y
DWR ID: DWR_RD2058_01_f_2012_4										
7	1.24	1.24	Earthen Levee	Encroachments	CRA/W	PI : Pipe Ma		37.802314 ° -121.401984 °	37.802314 ° -121.401984 °	22 Y
DWR ID: DWR_RD2058_01_s_2012_22										
8	1.69	1.72	Earthen Levee	Vegetation	WS	M Ma	V4 : Elderberries are blocking visibility and flood fight capability. Inspector Comments: Removal of this type of vegetation is currently prohibited by FWS.	37.804158 ° -121.394169 °	37.804329 ° -121.393612 °	961
DWR ID: DWR_RD2058_01_s_2012_961										

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	11/06/2012 11/06/2012	Maksim Khashchuk

LMR No.	Levee Mile		Category	Item	Location	Rating	Action/Comment	GPS Latitude/Longitude		Issue No.
	Start	End						Start	End	
9	2.15	2.15	Supplemental	DWR Erosion Survey	WS	M Ma	Inspector Comments: 07/31/2012: Site was visited on 07/26/2012. No significant change observed. A new vertical pipe was installed and concrete blocks left on the site. Dense vegetation around the site. No signs of new leaks or spill from the siphon breaker. 09/02/2011: Site was not visited due to the time limit. 09/22/2010: No significant changes observed. Vegetation downstream, upstream and on the lower slope of the site have been recently sprayed. These areas were also fenced off during the site visit, making it difficult for us to examine the condition of the lower slope. Possible leak or spill from the siphon breaker is creating notches along the slope and developing into a headward erosion. If the problem continues, it will erode the slope and fully expose the pipe to outside elements. 07/23/2009: A possible leak or spill from a siphon breaker is eroding the slope and developing into a headward erosion; a portion of the buried pipe is exposed; the lower slope seems to be lined with chunks of concrete debris or other rock material. [2012 Site ID:RD2058U01RM1.78]	37.803769 ° -121.386341 °	37.803769 ° -121.386341 °	1 Y
10	2.15	2.15	Earthen Levee	Encroachments	CRA/W	PI : Pipe Ma		37.803910 ° -121.386295 °	37.803910 ° -121.386295 °	23 Y
DWR ID: DWR_RD2058_01_s_2012_23										
11	2.42	2.42	Earthen Levee	Vegetation	LS A/W	V4 : Elderberries are blocking visibility and flood fight capability. Ma	Inspector Comments: Elderberry growing on landside toe.	37.802782 ° -121.381413 °	37.802782 ° -121.381413 °	16 Y
DWR ID: DWR_RD2058_01_s_2012_16										
12	2.64	2.64	Earthen Levee	Vegetation	WSA/W	V4 : Elderberries are blocking visibility and flood fight capability. Ma	Inspector Comments: Elderberry on water side slope.	37.801962 ° -121.377684 °	37.801962 ° -121.377684 °	63 Y
DWR ID: DWR_RD2058_01_s_2012_63										
13	2.66	2.66	Earthen Levee	Vegetation	WSA/W	V4 : Elderberries are blocking visibility and flood fight capability. Ma		37.801876 ° -121.377291 °	37.801876 ° -121.377291 °	64
DWR ID: DWR_RD2058_01_s_2012_64										
14	2.67	2.67	Earthen Levee	Vegetation	WSA/W	V4 : Elderberries are blocking visibility and flood fight capability. Ma		37.801823 ° -121.377068 °	37.801823 ° -121.377068 °	65
DWR ID: DWR_RD2058_01_s_2012_65										
15	2.76	2.76	Earthen Levee	Vegetation	WSA/W	V4 : Elderberries are blocking visibility and flood fight capability. Ma		37.801497 ° -121.375586 °	37.801497 ° -121.375586 °	66
DWR ID: DWR_RD2058_01_s_2012_66										
16	2.89	2.89	Earthen Levee	Encroachments	WSA/W	PI : Pipe Ma		37.800894 ° -121.373135 °	37.800894 ° -121.373135 °	24 Y
DWR ID: DWR_RD2058_01_s_2012_24										
17	3.41	3.41	Earthen Levee	Encroachments	CRA/W	PI : Pipe Ma	Inspector Comments: Drainage discharge.	37.796421 ° -121.366254 °	37.796421 ° -121.366254 °	27
DWR ID: DWR_RD2058_01_s_2012_27										
18	3.57	3.57	Earthen Levee	Vegetation	LS A/W	V4 : Elderberries are blocking visibility and flood fight capability. Ma		37.794396 ° -121.364944 °	37.794396 ° -121.364944 °	68
DWR ID: DWR_RD2058_01_s_2012_68										

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	11/06/2012 11/06/2012	Maksim Khashchuk

LMR No.	Levee Mile		Category	Item	Location * + Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End					Start	End	
19	3.76	3.76	Earthen Levee	Vegetation	WS Ma	V4 : Elderberries are blocking visibility and flood fight capability. Inspector Comments: Flagged bushes obstructing visibility and access	37.791856 ° -121.363514 °	37.791856 ° -121.363514 °	974
DWR ID: DWR_RD2058_01_s_2012_974									
20	3.77	3.77	Earthen Levee	Vegetation	WS Ma	V4 : Elderberries are blocking visibility and flood fight capability. Inspector Comments: Removal of this type of vegetation is currently prohibited by FWS.	37.791745 ° -121.363553 °	37.791745 ° -121.363553 °	939
DWR ID: DWR_RD2058_01_s_2012_939									
21	3.85	3.85	Earthen Levee	Vegetation	WSA/W Ob	V8 : Environmental Requirements. Inspector Comments: Revegetation site.	37.790807 ° -121.362905 °	37.790807 ° -121.362905 °	20 Y
DWR ID: DWR_RD2058_01_s_2012_20									
22	4.01	4.01	Earthen Levee	Vegetation	LS Ma	V4 : Elderberries are blocking visibility and flood fight capability. Inspector Comments: Elderberry on landside hinge point.	37.789128 ° -121.361042 °	37.789128 ° -121.361042 °	26 Y
DWR ID: DWR_RD2058_01_s_2012_26									
23	4.01	4.01	Earthen Levee	Vegetation	WSA/W Ma	V4 : Elderberries are blocking visibility and flood fight capability.	37.789096 ° -121.360966 °	37.789096 ° -121.360966 °	69
DWR ID: DWR_RD2058_01_s_2012_69									
24	4.36	4.36	Earthen Levee	Vegetation	WSA/W Ma	V4 : Elderberries are blocking visibility and flood fight capability.	37.789794 ° -121.354883 °	37.789794 ° -121.354883 °	71
DWR ID: DWR_RD2058_01_s_2012_71									
25	4.49	4.53	Supplemental	DWR Erosion Survey	WS Ma	Inspector Comments: 07/26/2012: The site has been visited, and no significant change has been observed. 09/02/2011: This site was not visited due to the time limit. 09/22/2010: No significant changes observed. Minor pocket erosions are lined at the lower bank. Two large Oak and Willow trees are on midslope and bench. The remaining bench was re-measured and found to be approximately 10 feet. There was no indication of active erosion on site during the site visit. 08/05/2010: Recommended for annual assessment and monitoring of site during flood events, per CLRO. 07/23/2009: No major change observed since last visit; site is a 200-ft. long near-vertical berm erosion; recommend annual assessment and monitoring of erosion site, per CLRO CES Evaluation 2008 Report; Site # is the same site previously reported as RM4.0,LM4.51; previously rated "U". 09/10/2008: Two large trees (2-3' DBH) with partial roots exposed. 2007: Visited site 03/13/2007. [2012 Site ID:RD2058U01RM3.97]	37.789810 ° -121.352490 °	37.789810 ° -121.352490 °	2 Y
DWR ID:									
26	5.16	5.16	Earthen Levee	Encroachments	LS En	RA : Ramp Inspector Comments: New Ramp construction Connecting Dairy to levee. Construction of ramp results in a new pond on the landside of the levee. 2/21/2012, owner has said that he will contact the CVFPB to resolve this issue.	37.783102 ° -121.345682 °	37.783102 ° -121.345682 °	29 Y
DWR ID: DWR_RD2058_01_s_2012_29									

* Location LS : Land Side WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	11/06/2012 11/06/2012	Maksim Khashchuk

LMR No.	Levee Mile		Category	Item	Location *	Rating ** + Rating	Action/Comment	GPS Latitude/Longitude		Issue No. Photo
	Start	End						Start	End	
27	5.37	5.37	Earthen Levee	Encroachments	LS	U En	RA : Ramp Inspector Comments: Ramp constructed to dairy. Raised ramps, see issue 29 are creating new holding ponds for dairy at levee toe.	37.782268 ° -121.342257 °	37.782268 ° -121.342257 °	30 Y
DWR ID: DWR_RD2058_01_s_2012_30										
28	6.06	6.06	Earthen Levee	Animal Control	WS	M Ma	A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.	37.775015 ° -121.335233 °	37.775015 ° -121.335233 °	5 Y
DWR ID: DWR_RD2058_01_f_2012_5										

*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	11/06/2012 11/06/2012	Maksim Khashchuk

Levee Mile Report Line	2
Start Levee Mile	
End Levee Mile	
Location	Land Side
Category	Earthen Levee
Item	Emergency Supplies & Equipment

View of flood fight supplies.

mkhashch_f_20121119_780.JPG



Levee Mile Report Line	4
Start Levee Mile	0.42
End Levee Mile	0.42
Location	Water Side
Category	Earthen Levee
Item	Vegetation

11/08/2011 Thick brush in this area needs to be taken back to 20' from hinge point.

mkhashch_f_20120927_657.jpg



Levee Mile Report Line	5
Start Levee Mile	0.73
End Levee Mile	0.73
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of discharge pipe on landside slope.

mkhashch_f_20121119_781.JPG



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	11/06/2012 11/06/2012	Maksim Khashchuk

Levee Mile Report Line	6
Start Levee Mile	0.96
End Levee Mile	0.96
Location	Land Side
Category	Earthen Levee
Item	Encroachments

View of prunings on landside slope.

mkhashch_f_20121119_782.JPG



Levee Mile Report Line	7
Start Levee Mile	1.24
End Levee Mile	1.24
Location	Crown
Category	Earthen Levee
Item	Encroachments

Drainage discharge to Paradise Cut.

mkhashch_f_20120927_660.jpg



Levee Mile Report Line	9
Start Levee Mile	2.15
End Levee Mile	2.15
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Close look at the site. Note the concrete blocks and vegetation.

SJR2012_RD2058U01RM1.78_1.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	11/06/2012 11/06/2012	Maksim Khashchuk

Levee Mile Report Line	9
Start Levee Mile	2.15
End Levee Mile	2.15
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Direct view of siphon breaker.

SJR2012_RD2058U01RM1.78_2.jpg



Levee Mile Report Line	10
Start Levee Mile	2.15
End Levee Mile	2.15
Location	Crown
Category	Earthen Levee
Item	Encroachments

Drainage discharge to Paradise Cut.

mkhashch_f_20120927_661.jpg



Levee Mile Report Line	11
Start Levee Mile	2.42
End Levee Mile	2.42
Location	Land Side
Category	Earthen Levee
Item	Vegetation

03/28/2012 Large elderberry bush on landside slope.

mkhashch_f_20120927_658.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	11/06/2012 11/06/2012	Maksim Khashchuk

Levee Mile Report Line	12
Start Levee Mile	2.64
End Levee Mile	2.64
Location	Water Side
Category	Earthen Levee
Item	Vegetation

03/28/2012 Large elderberry bush located on waterward slope.

mkhashch_f_20120927_668.jpg



Levee Mile Report Line	16
Start Levee Mile	2.89
End Levee Mile	2.89
Location	Water Side
Category	Earthen Levee
Item	Encroachments

Irrigation intake from Paradise Cut.

mkhashch_f_20120927_662.jpg



Levee Mile Report Line	21
Start Levee Mile	3.85
End Levee Mile	3.85
Location	Water Side
Category	Earthen Levee
Item	Vegetation

11/08/2011 Revegetation site, cannot trim or cut vegetation in this area.

mkhashch_f_20120927_659.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	11/06/2012 11/06/2012	Maksim Khashchuk

Levee Mile Report Line	22
Start Levee Mile	4.01
End Levee Mile	4.01
Location	Land Side
Category	Earthen Levee
Item	Vegetation

Elderberry bushes on landside slope.

mkhashch_f_20121119_783.JPG



Levee Mile Report Line	25
Start Levee Mile	4.49
End Levee Mile	4.53
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Direct view at a pocket erosion site. Vegetation has developed and covered the erosion.

SJR2012_RD2058U01RM3.97_1.jpg



Levee Mile Report Line	25
Start Levee Mile	4.49
End Levee Mile	4.53
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Direct view at a the erosion near a tree

SJR2012_RD2058U01RM3.97_2.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	11/06/2012 11/06/2012	Maksim Khashchuk

Levee Mile Report Line	25
Start Levee Mile	4.49
End Levee Mile	4.53
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Direct view at a the erosion near a tree

SJR2012_RD2058U01RM3.97_3.jpg



Levee Mile Report Line	25
Start Levee Mile	4.49
End Levee Mile	4.53
Location	Water Side
Category	Supplemental
Item	DWR Erosion Survey

Direct view at a the erosion near a tree

SJR2012_RD2058U01RM3.97_4.jpg



Levee Mile Report Line	26
Start Levee Mile	5.16
End Levee Mile	5.16
Location	Land Side
Category	Earthen Levee
Item	Encroachments

11/08/2011 New ramp has been constructed by Dairy farmer connecting his barns to the levee.

mkhashch_f_20120927_664.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	11/06/2012 11/06/2012	Maksim Khashchuk

Levee Mile Report Line	26
Start Levee Mile	5.16
End Levee Mile	5.16
Location	Land Side
Category	Earthen Levee
Item	Encroachments

11/08/2011 New ramp has been constructed by Dairy farmer connecting his barns to the levee.

mkhashch_f_20120927_665.jpg



Levee Mile Report Line	26
Start Levee Mile	5.16
End Levee Mile	5.16
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Completed new ramp constructed by Dairy farmer connecting his barns to the levee.

mkhashch_f_20121119_784.JPG



Levee Mile Report Line	27
Start Levee Mile	5.37
End Levee Mile	5.37
Location	Land Side
Category	Earthen Levee
Item	Encroachments

11/08/2011 Photo shows existing middle ramp to the levee which has been raised.

mkhashch_f_20120927_666.jpg



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Levee Inspection Report By Mile - Fall 2012

Reclamation District No. 2058 Pescadero

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Paradise Cut	Left	6.71	11/06/2012 11/06/2012	Maksim Khashchuk

Levee Mile Report Line	27
Start Levee Mile	5.37
End Levee Mile	5.37
Location	Land Side
Category	Earthen Levee
Item	Encroachments

11/08/2011 Photo shows view from the levee looking to the left of the middle ramp.

mkhashch_f_20120927_667.jpg



Levee Mile Report Line	27
Start Levee Mile	5.37
End Levee Mile	5.37
Location	Land Side
Category	Earthen Levee
Item	Encroachments

Completed new ramp constructed by Dairy farmer connecting his barns to the levee.

mkhashch_f_20121119_785.JPG



Levee Mile Report Line	28
Start Levee Mile	6.06
End Levee Mile	6.06
Location	Water Side
Category	Earthen Levee
Item	Animal Control

View of rodent burrows on waterside slope.

mkhashch_f_20121119_786.JPG



*** Location**

LS : Land Side
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable
M : Minimally Acceptable
U : Unacceptable
N : Not Inspected/Rated
C : Corrected
A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement